

FABRICATION/WELDING REQUIRED TOOLS & SUPPLIES LIST

FABRICATION WELDING 1

- Heavy Leather Boots with Safety Toe
- Safety Glasses (ANSI Z-87 standard)
- Leather Sleeves or Full Leather Jacket
- or Heavy Denim (cotton) Jacket
- Leather Gauntlet Gloves (lined)
- Cutting Goggles with Lenses
- Tip Cleaner
- Lock(s) for locker(s)
- 1"x25' Locking Tape Measure
- Soapstone with Holder
- Silver Pencil
- Wire Cutters or Side Cutters
- Slip Joint Pliers
- 6" Chisel
- Calculator (Scientific)
- Metric Rule
- Protractor
- Compass
- Clip Board
- 3-Ring Binder with Section Dividers
- 6" Center Punch
- Combination Square with 12" Rule
- Large Vise Grip Adjustable Clamp
- Small Vise Grip Adjustable Clamp
- Fillet Weld Gauge
- Striker
- Allen Wrench Set
- Chipping Hammer
- Wire Brush
- 2 Lb. Ball Peen Hammer

FABRICATION /WELDING 2

- All of the above tools & supplies for Fab/Weld 1
- Chalk Line (Plum Bob Type)
- Torpedo Level (Magnetic)
- Two Foot Framing Square
- 4 Lb. Hammer (Hand Sledge)
- 12" Adjustable Wrench with tapered end (Spud wrench)
- 10" Round File
- 10" Flat File
- Tool Box
- Electrode & Tip for Plasma Cutter
- T-Bevel Square

FABRICATION/WELDING 3

- All of the above tools & supplies for Fab/Weld 1 & 2
- Welding Hood with Lenses

FABRICATION WELDING 4

- All of the tools for Fab/Weld 1, 2, 3
- Trammel points with chalk/pencil holder
- Pipe wrap
- 4 1/2" Grinder
- 25' Extension cord
- Plate/sheetmetal Gauge
- Laser thermometer

TOTAL: \$765.00 (APPX.)