

2020 COVID-19 Water Testing Chlorine Follow-up

Building	Floor	Fixture	Location	Date Tested	Tested By	Results
Center	1st	16	Student Microwave Area	08/25/20	JAD	0.05
Center	2nd	3	200G Coffee Area	08/25/20	JAD	0.02
Center	3rd	1	328 Break Room	08/25/20	JAD	0.07
Center	4th	1	404 Staff Lounge	08/25/20	JAD	0.04
Center	4th	2	448 Staff Lounge	08/25/20	JAD	0.04
1	1st	1	126 Work Room	08/25/20	JAD	0.06
1	1st	2	115A Work Room	08/25/20	JAD	0.05
1	2nd	4	212 Conference Room	08/25/20	JAD	0.02
3	2nd	1	216A Coffee Room	08/25/20	JAD	0.27
4	1st	1	104	08/25/20	JAD	0.12
4	1st	1	123 West Faucet	08/25/20	JAD	0.06
4	2nd	1	232 Break Room	08/25/20	JAD	0.08
5	1st	1	102	08/25/20	JAD	0.10
5	1st	3	125	08/25/20	JAD	0.06
5	2nd	2	206A	08/25/20	JAD	0.05
7	2nd	1	209	08/25/20	JAD	0.42
8	1st	1	117 Conference Room	08/25/20	JAD	0.03
10	1st	6	131 Work Room	08/25/20	JAD	0.08
10	1st	12	108	08/25/20	JAD	0.05
11	2nd	1	245C Work Room	08/25/20	JAD	0.01
11	2nd	2	226 Staff Lounge	08/25/20	JAD	0.05
12	1st	2	121 Break Room	08/25/20	JAD	0.00
15	2nd	1	201A Kitchen	08/25/20	JAD	0.05
16	1st	3	164 Work Room	08/25/20	JAD	0.07
16	1st	52	115	08/25/20	JAD	0.05
16	2nd	1	205 Lunchroom	08/25/20	JAD	0.05
16	2nd	3	271	08/25/20	JAD	0.01
17	1st	1	101 Lobby	08/25/20	JAD	0.04
19	1st	16	143 Work Room	08/25/20	JAD	0.03
19	2nd	4	266B Lounge	08/25/20	JAD	0.04
30	1st	9	135	08/25/20	JAD	0.05
30	2nd	9	219	08/25/20	JAD	0.07
31	1st	2	103 Kitchen	08/25/20	JAD	0.13
61	1st	1	108	08/27/20	JAD	0.10
61	1st	6	131 Break Room	08/27/20	JAD	0.05
61	2nd	5	208 Work Room	08/27/20	JAD	0.23

61	3rd	6	326 Break Room	08/27/20	JAD	0.11
61	3rd	7	311 Work Room	08/27/20	JAD	0.48
61	4th	1	427 Break Room	08/27/20	JAD	0.05